

ATTACHMENT B-25

MAGNETS

- (A) B & H Curves are to be supplied which demonstrate compliance to drawing requirements
- (B) All magnets shall be packaged such that no contact is made between magnets to prevent damage during shipment.